


**GENERAL NOTES:**

1. Weld and Splice Interrupted Reinforcing Steel to Maintain Continuity of Reinforcement.
2. Shape Concrete Collar Over Connection.
3. Overlap Cut Surfaces Min. 3" and Apply Bonding Agent.